

# Errata Sheet

## Stall/Spin Awareness

25 September 2012

### Corrections (red underlined)

p. xiii, Figure 14-4: Anti-Spin Gyroscopic Effect...

p. 205, Table 13-1, Last Column, Calculated V-speeds: VS1 v n

p. 205, Table 13-1, Last Row, Note: 101 v (W2/1670)

p. 237, Figure 14-4, Caption: Anti-Spin Gyroscopic Effect...

p. 451, Appendix D:

Rich Stowell Consulting

P.O. Box 1026

McCall, ID 83638-1026, U.S.A.

(805) 218-0161

rich@richstowell.com

http://www.richstowell.com

## Deletions (strikethrough)

p. 451, Appendix D:

~~The National Association of Flight  
Instructors (NAFI)  
EAA Aviation Center  
P.O. Box 3086  
Oshkosh, WI 54903-3086  
(920) 426-6574, <http://www.nafinet.org>~~

## Insertions

p. 451, Appendix D:

Society of Aviation and Flight Educators  
(SAFE)  
<http://www.safepilots.org>  
**Member-centric organization open to all  
aviation educators**

Master Instructors LLC  
1803 Signature Court  
Longmont, CO 80504-2644  
303-485-8136,  
<http://www.masterinstructors.org>  
**The Master Instructor Program™**